



Runways

03/21: 3900 x 75 (ASPH-G)

Coordinates

Latitude 42-04-42.729N
Longitude 076-05-46.799W

Communications

CTAF/U 122.8
AWOS 119.075 (607) 785-2926
CLNC 121.7
APP/DEP 118.6 (BINGHAMTON)
PCL 122.8

Navigation

Elevation 833
NM from City 03 SW
Instr Approach NON-PRECISION

Owner/Manager

Owner VILLAGE OF ENDICOTT
Manager MR DOUGLAS GOODRICH
351 INDUSTRIAL PARK

Services

Fuel JETA 100LL 80
Airframe Repairs MAJOR
Engine MAJOR

Attended ALL/MON-FRI/0700-2100,ALL/
Airline Airport NO
Transportation
Food
Lodging

ENDICOTT NY 13760

Phone (607) 785-8353

Fax (607) 786-0692

E-mail

Web site

FBO (Location)

GOODRICH AVIATION & PILOT TRAINING CTR
(607) 785-8353

Remarks

TURF GLIDER STRIP ON EAST SIDE AND
PARALLEL TO RW 03/21; EXTENSIVE GLIDER
ACTIVITY. HIGH TERRAIN ALL QUADRANTS.
ROTG BEACON OBSCURED N & W OF ARPT
DUE TO HIGH TERRAIN.